SUBMIT THE FOLLOWING COMPLETED FORM TO YOUR LOCAL PLUMBING INSPECTOR Dube, Eugene

DATE May 1, 1973	OWNER Eugene Dube
NUMBER OF BEDROOMS 1	STREET Mount Vernon Road
SIZE OF SEPTIC TANK 1000	CITY Augusta, Maine MAINE
TYPE OF SOIL Sand	TEL. NUMBER NONE
Test Performed by [signature]	LOCATION OF PROPOSED INSTALLATION
Local Plumbing Inspector's Signature	STREET
	CITY Same MAINE
	TEL. NUMBER

SKETCH: LOCATION OF BUILDING DISPOSAL SYSTEM, TERRAIN FEATURES, PERCOLATION HOLES, WATER SUPPLIES, ETC.



REMARKS

Depth to Water Table
Depth to Bedrock
11' Depth to Clay or other impervious strata

HOLE	HOLE DEPTH	TIME START	TIME FINISH	DEPTH OF WATER SURFACE START	DEPTH OF WATER SURFACE FINISH	ELAPSED TIME	TOTAL DROP OF WATER	PERCOL. RATE MINUTES/INCH
#1	in.	10:00	10:20	12 in.	17 in.	20 min.	5 in.	4 min/in
#2	in.	10:04	10:30	12 in.	17 in.	26 min.	5 in.	5.1 min/in
#3	in.	10:09	10:33	12 in.	17 in.	24 min.	5 in.	4.9 min/in
#4	in.	10:15	10:37	12 in.	18 in.	22 min.	6 in.	3.1 min/in
							AVERAGE RATE	4.4 min/in