

Enclosed Materials

1. List of Oil Spills by Category from DEP Hazardous Oil

C.N. Brown spills highlighted in yellow

2. Actual Reports of spills

3. Water Contamination test results:

1997 & 2013

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results**Steps: 1 | 2**

The following reports are available for the search for:

Reported Date Range: **01/01/1988 - 02/11/2013**, Municipality: **AUGUSTA**, Tank Type: **Underground Tank(s) Involved**, Keywords: **riverside drive**

Please select the spill number of the report you wish to view. All reports are displayed in HTML (standard web page). If the spill number is not clickable, the spill report is pending.

Results: 1-16 of 16

Spill Number	Report Date	Town/MCD	Location	Spill Type	Tank Type
A-352-1993	Jul 15, 1993	AUGUSTA	IRVING OIL CIVIC...	Oil Incident	Underground Tank(s) Involved
A-553-1994	Nov 16, 1994	AUGUSTA	GLENRIDGE APARTMENTS...	Oil Incident	Underground Tank(s) Involved
A-338-1996	Jul 26, 1996	AUGUSTA	O'CONNOR GMC 187...	Oil Incident	Underground Tank(s) Involved
A-357-1996	Aug 6, 1996	AUGUSTA	FORMER LIPMAN POULTRY...	Oil Incident	Underground Tank(s) Involved
A-487-1996	Oct 31, 1996	AUGUSTA	IRVING OIL CIVIC...	Oil Incident	Underground Tank(s) Involved
A-17-1997	Jan 23, 1997	AUGUSTA	SCI TECHNOLOGY INC 500...	Oil Incident	Underground Tank(s) Involved
A-113-1997	Apr 14, 1997	AUGUSTA	JOSEPH KIRSCHNER CO...	Oil Incident	Underground Tank(s) Involved
A-335-1998	Jun 30, 1998	AUGUSTA	CMP NORTH AUGUSTA...	Oil Incident	Underground Tank(s) Involved
A-1-1999	Jan 1, 1999	AUGUSTA	GETTY PETROLEUM CORP....	Oil Incident	Underground Tank(s) Involved
A-45-2003	Jan 24, 2003 <i>New Bridge</i>	AUGUSTA	ME DOT 259 RIVERSIDE DR	Oil Incident	Underground Tank(s) Involved
A-162-2003	Apr 7, 2003	AUGUSTA	C N BROWN 362...	Oil Incident	Underground Tank(s) Involved
A-275-2004	May 13, 2004	AUGUSTA	C N BROWN BULK PLANT...	Oil Incident	Underground Tank(s) Involved
A-179-2007	Apr 17, 2007	AUGUSTA	FINE ARTS BLDG,...	Oil Incident	Underground Tank(s) Involved
A-651-2007	Oct 28, 2007	AUGUSTA	IRVING MAINWAY 262...	Oil Incident	Underground Tank(s) Involved
A-579-2008	Sep 12, 2008	AUGUSTA	LUK OIL 240 RIVERSIDE...	Oil Incident	Underground Tank(s) Involved
A-764-2008	Dec 13, 2008	AUGUSTA	UNIVERSITY OF MAINE AT...	Oil Incident	Underground Tank(s) Involved

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results

Steps: 1 | 2

The following reports are available for the search for:

Reported Date Range: **12/23/1980 - 02/11/2013**, Municipality: **AUGUSTA**, Tank Type: **Above Ground Tank(s) Involved**, Keywords: **riverside drive**

Please select the spill number of the report you wish to view. All reports are displayed in HTML (standard web page). If the spill number is not clickable, the spill report is pending.

Results: 1-23 of 23

Spill Number	Report Date	Town/MCD	Location	Spill Type	Tank Type
A-62-1995	Feb 22, 1995	AUGUSTA	CURTIS, SANDRA LOT 89...	Oil Incident	Above Ground Tank(s) Involved
A-345-1996	Jul 31, 1996	AUGUSTA	CN BROWN BULK PLANT...	Oil Incident	Above Ground Tank(s) Involved
A-504-1996	Nov 14, 1996	AUGUSTA	CN BROWN BULK PLANT...	Oil Incident	Above Ground Tank(s) Involved
A-12-1998	Jan 10, 1998	AUGUSTA	TEED, DAWN RIVERSIDE...	Oil Incident	Above Ground Tank(s) Involved
A-551-1998	Oct 6, 1998	AUGUSTA	NUCO2 569 RIVERSIDE DR	Hazardous Material Incident	Above Ground Tank(s) Involved
A-558-1999	Sep 11, 1999	AUGUSTA	ADAMS, MATILDA...	Oil Incident	Above Ground Tank(s) Involved
A-200-2000	Apr 6, 2000	AUGUSTA	ADAMS, MATILDA...	Oil Incident	Above Ground Tank(s) Involved
A-467-2000	Aug 23, 2000	AUGUSTA	CN BROWN BULK PLANT...	Oil Incident	Above Ground Tank(s) Involved
A-241-2001	Apr 6, 2001	AUGUSTA	DOIRON, ANDREW...	Oil Incident	Above Ground Tank(s) Involved
A-695-2004	Dec 18, 2004	AUGUSTA	MARC RODRIGUE 808...	Oil Incident	Above Ground Tank(s) Involved
A-609-2005	Dec 12, 2005	AUGUSTA	RED SHIELD BULK PLANT...	Oil Incident	Above Ground Tank(s) Involved
A-75-2006	Feb 2, 2006	AUGUSTA	JOHN NIMS 514...	Oil Incident	Above Ground Tank(s) Involved
A-136-2006	Mar 6, 2006	AUGUSTA	DHS OFFICE COMPLEX 442...	Oil Incident	Above Ground Tank(s) Involved
A-319-2007	Jun 7, 2007	AUGUSTA	HUTCHINSON RESIDENCE...	Oil Incident	Above Ground Tank(s) Involved
A-643-2007	Oct 22, 2007	AUGUSTA	BARBARA SCHNETZ 47...	Oil Incident	Above Ground Tank(s) Involved
A-475-2008	Jul 28, 2008	AUGUSTA	C&S MARKET 785...	Oil Incident	Above Ground Tank(s) Involved
A-9-2009	Jan 6, 2009	AUGUSTA	GALL RESIDENCE	Oil Incident	Above Ground Tank(s)

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

Steps: 1 | 2

SEARCH: Results

The following reports are available for the search for:

Reported Date Range: **01/01/1988 - 02/11/2013**, Municipality: **AUGUSTA**, Tank Type: **None**, Keywords: **riverside drive**

Please select the spill number of the report you wish to view. All reports are displayed in HTML (standard web page). If the spill number is not clickable, the spill report is pending.

Results: **1-25 of 31**

Next 25

Spill Number	Report Date	Town/MCD	Location	Spill Type	Tank Type
A-318-2004	Jun 4, 2004	AUGUSTA	C N BROWN BULK PLANT...	Oil Incident	None
A-319-2004	Jun 4, 2004	AUGUSTA	C N BROWN BULK PLANT...	Oil Incident	None
A-33-2005	Jan 18, 2005	AUGUSTA	C N BROWN BULK PLANT...	Oil Incident	None
A-300-2005	Jul 1, 2005	AUGUSTA	WASTE MANAGEMENT - ...	Oil Incident	None
A-334-2005	Jul 21, 2005	AUGUSTA	HOME DEPOT 26 STEVEN...	Hazardous Material Incident	None
A-47-2006	Jan 20, 2006	AUGUSTA	RESIDENTIAL DRIVEWAY...	Oil Incident	None
A-55-2006	Jan 23, 2006	AUGUSTA	CMP TRANSFORMER POLE...	Oil Incident	None
A-80-2006	Feb 5, 2006	AUGUSTA	HOME DEPOT STEPHEN...	Hazardous Material Incident	None
A-166-2006	Mar 23, 2006	AUGUSTA	DICK'S SPORTING GOODS...	Oil Incident	None
A-190-2006	Apr 8, 2006	AUGUSTA	HOME DEPOT STEPHEN...	Non-Oil, Non-Hazardous Incident	None
A-323-2006	Jun 15, 2006	AUGUSTA	CENTRAL MAINE POWER 83...	Oil Incident	None
A-328-2006	Jun 17, 2006	AUGUSTA	HOME DEPOT 26 STEPHEN...	Hazardous Material Incident	None
A-561-2006	Oct 5, 2006	AUGUSTA	HOME DEPOT STEPHEN...	Oil Incident	None
A-94-2007	Mar 5, 2007	AUGUSTA	CN BROWN 362 RIVERSIDE...	Oil Incident	None
A-239-2007	May 8, 2007	AUGUSTA	MULLEN VEHICLE CONY...	Oil Incident	None
A-250-2007	May 10, 2007	AUGUSTA	CENTRAL MAINE POWER...	Oil Incident	None
A-215-2007	May 29, 2007	AUGUSTA	DEP RAY BUILDING 28...	Hazardous Material Incident	None

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results

Steps: 1 | 2

The following reports are available for the search for:

Reported Date Range: **01/01/1979 - 02/11/2013**, Municipality: **AUGUSTA**, Tank Type: **Unknown/Unspecified**, Keywords: **riverside drive**

Please select the spill number of the report you wish to view. All reports are displayed in HTML (standard web page). If the spill number is not clickable, the spill report is pending.

Results: 1-19 of 19

Spill Number	Report Date	Town/MCD	Location	Spill Type	Tank Type
A-141-1988	Apr 19, 1988	AUGUSTA		Oil Incident	Unknown/Unspecified
A-58-1989	Feb 6, 1989	AUGUSTA		Oil Incident	Unknown/Unspecified
A-416-1991	Aug 26, 1991	AUGUSTA		Oil Incident	Unknown/Unspecified
A-148-1993	Mar 23, 1993	AUGUSTA	AUGUSTA CIVIC CENTER...	Oil Incident	Unknown/Unspecified
A-282-1993	Jun 2, 1993	AUGUSTA	ELLIS, BOYD 330...	Non-Oil, Non-Hazardous Incident	Unknown/Unspecified
A-363-1993	Jul 21, 1993	AUGUSTA	RIVERSIDE TRAILER PARK...	Oil Incident	Unknown/Unspecified
A-146-1994	Apr 7, 1994	AUGUSTA	HALPERIN, BARBARA LOT...	Oil Incident	Unknown/Unspecified
A-338-1994	Jul 19, 1994	AUGUSTA	SHERWOOD ENTERPRISES...	Oil Incident	Unknown/Unspecified
A-510-1994	Oct 30, 1994	AUGUSTA	SHERWOOD ENTERPRISES...	Oil Incident	Unknown/Unspecified
A-401-1995	Aug 17, 1995	AUGUSTA	CMP TRANSFORMER #10...	Oil Incident	Unknown/Unspecified
A-331-1997	Sep 8, 1997	AUGUSTA	LOCSIN, SUSAN 342...	Oil Incident	Unknown/Unspecified
A-451-1997	Nov 3, 1997	AUGUSTA	JOSEPH KIRSCHNER...	Oil Incident	Unknown/Unspecified
A-175-1998	Mar 16, 1998	AUGUSTA	CMP TRANSFORMER, POLE...	Oil Incident	Unknown/Unspecified
B-378-1999	Jul 5, 1999	AUGUSTA	CMP TRANSFORMER /...	Oil Incident	Unknown/Unspecified
A-170-2000	Mar 24, 2000	AUGUSTA	CN BROWN BULK PLANT...	Oil Incident	Unknown/Unspecified
A-195-2000	Apr 4, 2000	AUGUSTA	CN BROWN BULK PLANT...	Oil Incident	Unknown/Unspecified
A-301-2000	May 25, 2000	AUGUSTA	DRIVEWAY OF DON...	Oil Incident	Unknown/Unspecified

7/31/1996

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full ReportSelected Report: **A-345-1996****Spill Report Information**

Spill Number: A-345-1996
 Report Status: Final Report
 MCD Town: AUGUSTA
 Local Name:
 Primary Responder: JON ANDREWS
 Primary Product:
 Subject/Owner: C.N. BROWN - -
 I. EVENT

Spill Info

Type: Oil Incident
 Source:
 Cause: Overfill

Spill Date/Time

Spill Date/Time: 07/31/1996

Reporter Type/Detection Method

Type: Subject/Spiller {2}
 Method: Visual Product

Reported Date/Time

Reported Date/Time: 07/31/1996 00:00

Subject/Spiller

Contact: C.N. BROWN
 362 RIVERSIDE DRIVE
 AUGUSTA ME 04330

Comment:

Primary Responder and Other Employees

Contact(s): JON ANDREWS (Primary Responder)
 Comment: No Further Response Action Expected

II. SITE**Location**

Location Type: Terminal - Bulk Plant {BP}
 Name: CN BROWN BULK PLANT
 Street Address: 362 RIVERSIDE DRIVE
 MCD Town: AUGUSTA
 Local Name:
 State/Province:

Land Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk
Land Affected: Land {L}

Tanks Involved

Tanks Involved: Above Ground Tank(s) Involved-Tank Outside

III. CLEANUP

Product Reported: #2 Fuel Oil {02}
Products Found/Amount Spilled: #2 Fuel Oil {02} - 8.00 ACTUAL
Material Recovered: Mixed Liquid Media {MM} - 8.00 gals. ACTUAL
Recovery/Treatment Method: Excavation {G} Sorbents {C}
Cleanup DTREE:
Disposal Information: remediation conducted by C N Brown staff

IV. NARRATIVE

DEP received a report that 5-10 gallons of heating oil was spilled during the overfill of a vehicle at this bulk oil terminal. According to the reporting individual (Alexander) the spill was entirely cleaned up. Contaminated soils were reportedly transported to the C N Brown main office. No site visit was conducted by DEP personnel as a result of this incident.

V. ATTACHMENTS

None

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

11/14/1996

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: **A-504-1996**

Spill Report Information

Spill Number: A-504-1996
Report Status: Final Report
MCD Town: AUGUSTA
Local Name:
Primary Responder: FRANCIS GEHLING
Primary Product:
Subject/Owner: C.N. BROWN - -

I. EVENT

Spill Info

Type: Oil Incident
Source:
Cause: Other - Unknown

Spill Date/Time

Spill Date/Time: Date and Time Unknown

Reporter Type/Detection Method

Type: Contractor/Consultant {6}
Method: Tank and/or Piping Removal

Reported Date/Time

Reported Date/Time: 11/14/1996 00:00

Subject/Spiller

Contact: C.N. BROWN
P.O. BOX 200
SOUTH PARIS ME 04281

Comment:

Primary Responder and Other Employees

Contact(s): FRANCIS GEHLING (Primary Responder)
Comment: No Further Response Action Expected

II. SITE

Location

Location Type: Terminal - Bulk Plant {BP}
Name: CN BROWN BULK PLANT
Street Address: 362 RIVERSIDE DRIVE
MCD Town: AUGUSTA
Local Name:
State/Province:

Spill Point

Spill Point:

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Land {L}

Tanks Involved

Tanks Involved: Above Ground Tank(s) Involved-Tank Outside

III. CLEANUP

Product Reported: #2 Fuel Oil {02}

Products Found/Amount Spilled: #2 Fuel Oil {02} - 0.00 UNKNOWN

Material Recovered: Mixed Liquid Media {MM} - 0.00 gals. UNKNOWN

Recovery/Treatment Method: Excavation {G}

Cleanup DTREE:

Disposal Information: D-Tree=BL1. Soil from under AST's was taken to Dragon Cement in Thomaston for disposal.

IV. NARRATIVE

See attached narrative for additional details.

V. ATTACHMENTS

None

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

9108141

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: **A-331-1997**

Spill Report Information

Spill Number: A-331-1997
 Report Status: Final Report
 MCD Town: AUGUSTA
 Local Name:
 Primary Responder: JON ANDREWS
 Primary Product:
 Subject/Owner: - SUSAN LOCSIN -

IL. EVER

Spill Info

Type: Oil Incident
 Source:
 Cause: Other - Unknown

Spill Date/Time

Spill Date/Time: Date and Time Unknown

Reporter Type/Detection Method

Type: Citizen Complaint {3}
 Method: Water Analysis/Complaint

Reported Date/Time

Reported Date/Time: 09/08/1997 00:00

Subject/Spiller

Contact: SUSAN LOCSIN-
 342 RIVERSIDE DRIVE
 AUGUSTA ME 04330

Comment:

Primary Responder and Other Employees

Contact(s): JON ANDREWS (Primary Responder)
 Comment: No Further Response Action Expected

IL. SITE

Location

Location Type: Residential - Single Family {SF}
 Name: LOCSIN, SUSAN
 Street Address: 342 RIVERSIDE DRIVE
 MCD Town: AUGUSTA
 Local Name:
 State/Province:

Spill Point

Spill Point: UTM North 4909811.65
UTM East 439597.91

Wells and Media Affected

Wells Affected: 1 Well Impacted/ 1 Well At Risk
Media Affected: Groundwater {G}

Tanks Involved

Tanks Involved: NONE

III. CLEANUP

Product Reported: Unspecified Oil {80}
Products Found/Amount Spilled: Unspecified Oil {80} - 0.00 UNKNOWN
Material Recovered: Mixed Liquid Media {MM} - 0.00 gals. ACTUAL
Recovery/Treatment Method: None {K}
Cleanup DTREE:
Disposal Information: D-tree categorization unclear

IV. NARRATIVE

DEP received a report from a homeowner (Locsin) that lab analysis on her water showed the presence of low concentrations of petroleum. Jon Andrews (DEP) visited the property on 9/9/97; odors were evident in water at the kitchen tap, and water sampled this day confirmed the presence of diesel range hydrocarbons at concentrations below the DEP action level.

The well (drilled) is relatively new. The neighborhood is residential/commercial and is served by the Augusta municipal water system. The subject property is currently not connected to that system; it appears that all other residences in this area are connected. I observed no obvious sources of contamination within 300' of this well; however, a bulk oil terminal with historical contamination (ref A-504-96) is located within 1000'. I referred this case for Tech Services attention, and anticipate no further Response involvement.

V. ATTACHMENTS

None

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)

Info@ME

Copyright © 2005 All rights reserved.

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results**Steps: 1 | 2**

The following reports are available for the search for:

Reported Date Range: **01/01/1996 - 01/01/1998**, Municipality: **AUGUSTA**, Tank Type: **Unknown/Unspecified**, Keywords: **riverside drive**

Please select the spill number of the report you wish to view. All reports are displayed in HTML (standard web page). If the spill number is not clickable, the spill report is pending.

Results: **1-2 of 2**

Spill Number	Report Date	Town/MCD	Location	Spill Type	Tank Type
A-331-1997	Sep 8, 1997	AUGUSTA	LOCSIN, SUSAN 342...	Oil Incident	Unknown/Unspecified
A-451-1997	Nov 3, 1997	AUGUSTA	JOSEPH KIRSCHNER...	Oil Incident	Unknown/Unspecified

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

Mr. Andrey Kuryevich Fink

Accompanied by:

Augusta, ME - Delegate Profiles

2/27/2000

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: **A-170-2000**

Full Report Information

Spill Number: A-170-2000
Report Status: Final Report
MCD Town: AUGUSTA
Local Name:
Primary Responder: MARY JAMES
Primary Product:
Subject/Owner: - BROWN CN -

EVENT

Spill Info

Type: Oil Incident
Source:
Cause: Other - Known Cause

Spill Date/Time

Spill Date/Time: 03/24/2000 00:00

Reporter Type/Detection Method

Type: Subject/Spiller {2}
Method: Visual Product

Reported Date/Time

Reported Date/Time: 03/24/2000 00:00

Subject/Spiller

Contact: BROWN CN-
PO BOX 200
SOUTH PARIS ME 04281

Comment:

Primary Responder and Other Employees

Contact(s): MARY JAMES (Primary Responder)
Comment: No Further Response Action Expected

LOCATION

Location

Location Type: Transportation - Road {RD}
Name: CN BROWN BULK PLANT
Street Address: 362 RIVERSIDE DRIVE
MCD Town: AUGUSTA
Local Name:
State/Province:

Oil Point:

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Land {L}

Tanks Involved

Tanks Involved: NONE

CLEANUP

Product Reported: #2 Fuel Oil {O2}

Products Found/Amount Spilled: #2 Fuel Oil {O2} - 2.00 ESTIMATE

Material Recovered: Mixed Liquid Media {MM} - 2.00 gals. ESTIMATE

Recovery/Treatment Method: Sorbents {C}

Cleanup DTREE:

Disposal Information: Sorbents added to CN Brown waste stream

NARRATIVE

A truck was loading at the racks when the air eliminator stuck. Product squirted out the valve onto the cement pad. Sorbent pads and speedy dri were used to clean up the oil.

No site visit made. No further action required by Response Services.

ATTACHMENTS

None

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov



Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full ReportSelected Report: **A-195-2000****Spill Report Information**

Spill Number: A-195-2000

Report Status: Final Report

MCD Town: AUGUSTA

Local Name:

Primary Responder: GLEN WALL

Primary Product:

Subject/Owner: - BROWN CN -

AGENT

Spill Info

Type: Oil Incident

Source:

Cause: Mechanical Failure - Valve

Spill Date/Time

Spill Date/Time: 04/04/2000

Reporter Type/Detection Method

Type: Subject/Spiller {2}

Method: Visual Product

Reported Date/Time

Reported Date/Time: 04/04/2000 00:00

Subject/SpillerContact: BROWN CN-
PO BOX 200
PARIS ME 04281

Comment:

Primary Responder and Other Employees

Contact(s): GLEN WALL (Primary Responder)

Comment: No Further Response Action Expected

II. SITE**Location**

Location Type: Transportation - Road {RD}

Name: CN BROWN BULK PLANT

Street Address: 362 RIVERSIDE DRIVE

MCD Town: AUGUSTA

Local Name:

State/Province:

Print:

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk
Media Affected: Land {L}

Tanks Involved

Tanks Involved: NONE

CLEANUP

Product Reported: Gasoline Unspecified {20}
Products Found/Amount Spilled: Gasoline Unspecified {20} - 15.00 ESTIMATE
Material Recovered: Mixed Liquid Media {MM} - 15.00 gals. ESTIMATE
Recovery/Treatment Method: Excavation {G} Sorbents {C}

Cleanup DTREE:

Disposal Information: soil disposal at Commercial Paving/Commerical Recycling Systems

EXPLANATION

An employee of C.N.Brown called this office to report a gasoline spill at the bulk plant located on Riverside Drive in Augusta. A fitting leak on the transport truck developed a leak, thus resulting in the release of about 15 gallons of gasoline. The contaminated soil was excavated by hand and eventually transported to Commercial Paving for disposal. No further action will be required.

ATTACHMENTS

None

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

8/23/2000

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: **A-467-2000**

Spill Report Information

Spill Number: A-467-2000
Report Status: Final Report
MCD Town: AUGUSTA
Local Name:
Primary Responder: FRANCIS GEHLING
Primary Product: Unleaded Gasoline {23} - 75.00 ACTUAL
Subject/Owner: - BROWN CN -

EVENT

Spill Info

Type: Oil Incident
Source:
Cause: Mechanical Failure - Piping/Hose

Spill Date/Time

Spill Date/Time: 08/23/2000

Reporter Type/Detection Method

Type: Subject/Spiller {2}
Method: Visual Product

Reported Date/Time

Reported Date/Time: 08/23/2000 00:00

Subject/Spiller

Contact: BROWN CN-
SOUTH PARIS ME 04281

Comment:

Primary Responder and Other Employees

Contact(s): FRANCIS GEHLING (Primary Responder)
Comment: No Further Response Action Expected

UT SITE

Location

Location Type: Terminal - Bulk Plant {BP}
Name: CN BROWN BULK PLANT
Street Address: 362 RIVERSIDE DRIVE
MCD Town: AUGUSTA

Local Name:
State/Province:

Spill Point

Point:

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Land {L}

Tanks Involved

Tanks Involved: Above Ground Tank(s) Involved-Tank Outside

III. CLEANUP

Product Reported: Unleaded Gasoline {23}

Products Found/Amount Spilled: Unleaded Gasoline {23} - 75.00 ACTUAL (Primary Product)

Material Recovered: Contaminated Soil {CS} - 45.73 tons ESTIMATE

Recovery/Treatment Method: Excavation {G}

Cleanup DTREE:

Disposal Information: Commercial Recycling

IV. NARRATIVE

Received a call from Kevin Moore of CN Brown that they had a gasoline spill at their Augusta bulk plant. I responded to the site. I found a large patch of wet ground, soaked with gasoline. A CN Brown maintenance employee was there and told me what happened. Apparently a large peddle truck was loading gasoline and one of the hoses blew, spilling about 50-75 gallons of gasoline. The area it spilled was not paved, so cleanup will consist of excavating the contaminated soil. I later met Leonard Carr on site, a contractor for CN Brown who would do the excavation. He excavated about 25 cubic yards of soil and I inspected the excavation prior to backfilling. No further work is necessary on this site.

V. ATTACHMENTS

None

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: **A-162-2003**

Report Information	
Spill Number:	A-162-2003
Report Status:	Final Report
MCD Town:	AUGUSTA
Local Name:	AUGUSTA
Primary Responder:	DANIEL E DAVIS
Primary Product:	#2 Fuel Oil {02} - 0.00 UNKNOWN
Subject/Owner:	C N BROWN - -
Spill Info	
Type:	Oil Incident
Source:	Storage Unit - <u>Underground Storage Tank</u>
Cause:	Overfill
Spill Date/Time	
Spill Date/Time:	Date and Time Unknown
Reporter Type/Detection Method	
Type:	Subject/Spiller {2}
Method:	Odor/Vapor/Mist
Reported Date/Time	
Reported Date/Time:	04/07/2003 00:00
Subject/Spiller (Potential Responsible Party)	
Contact:	C N BROWN PO BOX 200 164 MAIN ST EXT SO PARIS ME 04281 USA
Comment:	
Primary Responder and Other Employees	
Contact(s):	DANIEL E DAVIS (Primary Responder)
Comment:	No Further Response Action Expected
Location	
Location Type:	Terminal - Bulk Plant {BP}
Name:	C N BROWN
Street Address:	362 RIVERSIDE DR
MCD Town:	AUGUSTA
Local Name:	AUGUSTA

ce:

ME

it

int:

UTM North 4909907.54
UTM East 439661.76

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Underground Tank(s) Involved-8941 0

CLEANUP

Product Reported:

#2 Fuel Oil {02}

Products Found/Amount Spilled:

#2 Fuel Oil {02} - 0.00 UNKNOWN (Primary Product)

Material Recovered:

Contaminated Soil {CS} - 2.29 tons ACTUAL

Recovery/Treatment Method:

Excavation {G}

Cleanup DTREE:

Disposal Information:

CRS

7. NARRATIVE

An employee found oil stains near a vent pipe for the heating oil UST after the snow melted. LC Tanks was hired to excavate oily soil. An underground portion of the vent line is of a corrugated material so some product is likely still in the horizontal portion of the vent line and will be ejected during tank fills for some time to come. LC Tanks installed sorbents on the vent line to attempt to collect the spray as it comes out. C.N.Brown will maintain the sorbent system.

ATTACHMENTS

Attachment Type

Description

Paper Attach

crs report

Paper Attach

virgin letter

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

5/13/2004

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: **A-275-2004**

III Report Information

Spill Number: A-275-2004
 Report Status: Final Report
 MCD Town: AUGUSTA
 Local Name: AUGUSTA
 Primary Responder: GLEN WALL
 Primary Product: Gasoline Unspecified {20} - 40.00 ESTIMATE
 Subject/Owner: C N BROWN - -

Spill Info

Type: Oil Incident
 Source: Land Transportation - Tank Truck
 Cause: Mechanical Failure - Piping/Hose

Spill Date/Time

Spill Date/Time: 05/13/2004

Reporter Type/Detection Method

Type: Subject/Spiller {2}
 Method: Visual Product

Reported Date/Time

Reported Date/Time: 05/13/2004 00:00

Subject/Spiller (Potential Responsible Party)

Contact: C N BROWN
 PO BOX 200
 164 MAIN ST EXT
 SO PARIS ME 04281 USA

Comment:

Primary Responder and Other Employees

Contact(s): GLEN WALL (Primary Responder)
 Comment: No Further Response Action Expected

IV. SITE

Location

Location Type: Terminal - Bulk Plant {BP}
 Name: C N BROWN BULK PLANT
 Street Address: 360 RIVERSIDE DR
 MCD Town: AUGUSTA
 Local Name: AUGUSTA

ice:

ME

nt

oint:

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Above Ground Tank(s) Involved-Tank Outside

PRODUCTS AND CLEANUP

Product Reported:

Gasoline Unspecified {20}

Products Found/Amount Spilled:

Gasoline Unspecified {20} - 40.00 ESTIMATE (Primary Product)

Material Recovered:

Contaminated Soil {CS} - 29.21 tons ACTUAL

Recovery/Treatment Method:

Excavation {G}

Cleanup DTREE:

Disposal Information:

29 tons excavated and transported to CP/CRS

NARRATIVE

On 5-13-04, CN Brown reported the release of about 40 gallons of gasoline. This spill was the result of a hose failure while off loading gasoline from a transport truck. The gasoline spilled onto the ground. CN Brown hired EPI to excavate the soil and transport it to Commercial Paving. No further action will be required.

ATTACHMENTS

Attachment Type

Description

Paper Attach

CRS Generator Form

Paper Attach

Contaminated Soil Letter, a DEP form

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

06/04/2004

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: A-318-2004

I. Report Information

Spill Number: A-318-2004
Report Status: Final Report
MCD Town: AUGUSTA
Local Name: AUGUSTA
Primary Responder: PETER J BLANCHARD
Primary Product: Diesel {29} - 5.00 ESTIMATE
Subject/Owner: C N BROWN - -

II. EVENT

Spill Info

Type: Oil Incident
Source: Storage Unit - Aboveground Storage Tank
Cause: Overfill

Spill Date/Time

Spill Date/Time: 06/04/2004 00:00

Reporter Type/Detection Method

Type: Subject/Spiller {2}
Method: Visual Product

Reported Date/Time

Reported Date/Time: 06/04/2004 00:00

Subject/Spiller (Potential Responsible Party)

Contact: C N BROWN
PO BOX 200
164 MAIN ST EXT
SO PARIS ME 04281 USA

Comment:

Primary Responder and Other Employees

Contact(s): PETER J BLANCHARD (Primary Responder)
Comment: No Further Response Action Expected

III. SITE

Location

Location Type: Terminal - Bulk Plant {BP}
Name: C N BROWN BULK PLANT
Street Address: 362 RIVERSIDE DR
MCD Town: AUGUSTA
Local Name: AUGUSTA

Province:

ME

Point:

Wells and Media Affected

0 Wells Impacted/ 0 Wells At Risk

Wells Affected:

Land {L}

Media Affected:

Tanks Involved

Tanks Involved:

Undefined

WELL CLEANUP

Product Reported:

Diesel {29}

Products Found/Amount Spilled:

Diesel {29} - 5.00 ESTIMATE (Primary Product)

Material Recovered:

Other Material {OM} - 4.75 gals. ESTIMATE

Recovery/Treatment Method:

Sorbents {C}

Cleanup DTREE:

Disposal Information:

By spiller

7. NARRATIVE

Paula, one of the people from C.N. Brown, called to report an overfill at their bulk plant in Augusta. The plant has an outdoor diesel AST. A driver was filling the tank from a delivery tank truck and overfilled it. He sprayed about 5 gallons down the sides of the tank and onto the ground before he could put out his cigarette and shut the pump down. Several more of the people from C.N. Brown got down on their knees and padded up the spilled oil. It sounded like an awesome time, but I guessed they had it under control, so no site visit was conducted.

ATTACHMENTS

None

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: **A-319-2004**

Spill Report Information

Spill Number: A-319-2004
 Report Status: Final Report
 MCD Town: AUGUSTA
 Local Name: AUGUSTA
 Primary Responder: JON ANDREWS
 Primary Product: Diesel {29} - 0.10 ESTIMATE
 Subject/Owner: C N BROWN - -

EVENT

Spill Info

Type: Oil Incident
 Source: Land Transportation - Tank Truck
 Cause: Accident - Human Error

Spill Date/Time

Spill Date/Time: 06/04/2004

Reporter Type/Detection Method

Type: Subject/Spiller {2}
 Method: Visual Product

Reported Date/Time

Reported Date/Time: 06/04/2004 00:00

Subject/Spiller (Potential Responsible Party)

Contact: C N BROWN
 PO BOX 200
 164 MAIN ST EXT
 SO PARIS ME 04281 USA

Comment:

Primary Responder and Other Employees

Contact(s): JON ANDREWS (Primary Responder)
 Comment: No Further Response Action Expected

II. SITE

Location

Location Type: Terminal - Bulk Plant {BP}
 Name: C N BROWN BULK PLANT
 Street Address: 362 RIVERSIDE DR
 MCD Town: AUGUSTA
 Local Name: AUGUSTA

Province:

ME

Oil Point

Oil Point:

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Undefined

III. CLEANUP

Product Reported:

Diesel {29}

Products Found/Amount Spilled:

Diesel {29} - 0.10 ESTIMATE (Primary Product)

Material Recovered:

Other Material {OM} - 0.10 gals. ESTIMATE

Recovery/Treatment Method:

Sorbents {C}

Cleanup DTREE:

Disposal Information:

by spiller

IV. NARRATIVE

DEP received a report that a small amount of oil spilled to pavement from an oil tanker at this facility. According to the reporter, the spill was immediately cleaned up with the use of sorbent material.

V. COMMENTS

None

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

DEPARTMENT OF ENVIRONMENTAL PROTECTION
Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: **A-33-2005**

I. Report Information

Spill Number: A-33-2005
 Report Status: Final Report
 MCD Town: AUGUSTA
 Local Name: AUGUSTA
 Primary Responder: GLEN WALL
 Primary Product: #1 Fuel Oil - Kerosene {01} - 0.50 ESTIMATE
 Subject/Owner: C N BROWN - -

II. Spill Info

Type: Oil Incident
 Source: Land Transportation - Tank Truck
 Cause: Overfill

Spill Date/Time

Spill Date/Time: 01/18/2005

Reporter Type/Detection Method

Type: Subject/Spiller {2}
 Method: Visual Product

Reported Date/Time

Reported Date/Time: 01/18/2005 00:00

Subject/Spiller (Potential Responsible Party)

Contact: C N BROWN
 PO BOX 200
 164 MAIN ST EXT
 SO PARIS ME 04281 USA

Comment:

Primary Responder and Other Employees

Contact(s): GLEN WALL (Primary Responder)
 Comment: No Further Response Action Expected

II. SITE

Location

Location Type: Terminal - Bulk Plant {BP}
 Name: C N BROWN BULK PLANT
 Street Address: RIVERSIDE DR
 MCD Town: AUGUSTA
 Local Name: AUGUSTA

ate/Province:

ME

Spill Point

Spill Point:

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Land {L}

Tanks Involved

Tanks Involved: Above Ground Tank(s) Involved-Tank Outside

CLEANUP

Product Reported: #1 Fuel Oil - Kerosene {01}

Products Found/Amount Spilled: #1 Fuel Oil - Kerosene {01} - 0.50 ESTIMATE (Primary Product)

Material Recovered: Other Material {OM} - 2.00 lbs. ESTIMATE Contaminated Soil {CS} - 5.00 lbs. ESTIMATE

Recovery/Treatment Method: Sorbents {C} Excavation {G}

Cleanup DTREE:

Disposal Information: soil and pads disposed of by C N Brown

EXPLANATIVE

On 1-18-2005, C N Brown reported the release of 1/2 gallon of kerosene. This occurred at their bulk oil plant on Riverside Drive in Augusta. The oil delivery truck was overfilled and some of the oil went out the vent onto the truck and onto the ground. The driver cleaned up the spill with sorbent material and hand-excavating a small amount of soil.

No further action will be required.

ATTACHMENTS

None

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

12/12/2005

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: **A-609-2005**

Spill Report Information

Spill Number: A-609-2005
Report Status: Final Report
MCD Town: AUGUSTA
Local Name: AUGUSTA
Primary Responder: PETER J BLANCHARD
Primary Product: #2 Fuel Oil {02} - 1.00 ESTIMATE
Subject/Owner: C N BROWN - -

Spill Info

Type: Oil Incident
Source: Land Transportation - Tank Truck
Cause: Overfill

Spill Date/Time

Spill Date/Time: 12/12/2005 00:00

Reporter Type/Detection Method

Type: Subject/Spiller {2}
Method: Visual Product

Reported Date/Time

Reported Date/Time: 12/12/2005 00:00

Subject/Spiller (Potential Responsible Party)

Contact: C N BROWN
PO BOX 200
164 MAIN ST EXT
SO PARIS ME 04281 USA

Comment:

Primary Responder and Other Employees

Contact(s): PETER J BLANCHARD (Primary Responder)
Comment: No Further Response Action Expected

IL SITE

Location

Location Type: Terminal - Bulk Plant {BP}
Name: RED SHIELD BULK PLANT
Street Address: 362 RIVERSIDE DR
MCD Town: AUGUSTA
Local Name: AUGUSTA

Province:

ME

Point

Well Point:

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Above Ground Tank(s) Involved-Tank Outside

WELL CLEANUP

Product Reported:

#2 Fuel Oil {02}

Products Found/Amount Spilled:

#2 Fuel Oil {02} - 1.00 ESTIMATE (Primary Product)

Material Recovered:

Other Material {OM} - 1.00 gals. ESTIMATE

Recovery/Treatment Method:

Sorbents {C}

Cleanup DTREE:

Disposal Information:

Disposal by C.N. Brown

WELL NARRATIVE

Paula called from C.N. Brown to report an overfill of #2 fuel oil at their bulk plant in Augusta. The driver filling the delivery truck failed to shut down the fill on the loading rack overtopping the tank slightly. An estimated 1 gallon drained through the precipitation drain holes on the rollover protection/containment on top of the truck. This oil spilled to concrete and was wiped up with sorbent pads. I called Charlotte on site at the plant and she confirmed the small nature of the spill and cleanup. No site visit was made.

ATTACHMENTS

None

[Back to Results](#)

[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.

3/4/2007

Hazardous & Oil Spill System
ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: **A-94-2007**

Spill Report Information

Spill Number:	A-94-2007
Report Status:	Final Report
MCD Town:	AUGUSTA
Local Name:	AUGUSTA
Primary Responder:	GLEN WALL
Primary Product:	Gasoline Unspecified {20} - 8.00 ESTIMATE
Subject/Owner:	C N BROWN - -

Spill Info

Type:	Oil Incident
Source:	Land Transportation - Tank Truck
Cause:	Other - Known Cause

Spill Date/Time

Spill Date/Time: 03/04/2007 00:00

Reporter Type/Detection Method

Type:	Subject/Spiller {2}
Method:	Visual Product

Reported Date/Time

Reported Date/Time: 03/05/2007 00:00

Subject/Spiller (Potential Responsible Party)

Contact: C N BROWN
PO BOX 200
164 MAIN ST EXT
SO PARIS ME 04281 USA

Comment:

Primary Responder and Other Employees

Contact(s):	GLEN WALL (Primary Responder)
Comment:	No Further Response Action Expected

II. SITE

Location

Location Type:	Terminal - Bulk Plant {BP}
Name:	CN BROWN
Street Address:	362 RIVERSIDE DRIVE
MCD Town:	AUGUSTA
Local Name:	AUGUSTA

State/Province:

ME

Spill Point

Spill Point:

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Undefined

III. CLEANUP

Product Reported:

Gasoline Unspecified {20}

Products Found/Amount Spilled:

Gasoline Unspecified {20} - 8.00 ESTIMATE (Primary Product)

Material Recovered:

Contaminated Soil {CS} - 0.54 tons ACTUAL

Recovery/Treatment Method:

Excavation {G}

Cleanup DTREE:

Disposal Information:

Through EPI to CPRC in Scarborough

IV. NARRATIVE

DEP received a report from CN Brown that approximately 8 gallons of gasoline had spilled from a tank truck at their bulk plant. The truck had a hole in one of the tank pockets. The gasoline was emptied back into the Underground Storage Tank. I went to the site late in the afternoon on the 5th and found that 2 inches below grade there was still a very strong odor of gasoline. EPI was contracted by CN Brown to excavate the contaminated soil. Approximately one half ton of soil was removed and transported to Commercial Paving & Recycling Company (CPRC) in Scarborough. No further Response action expected at this time.

V. ATTACHMENTS

Attachment Type

Description

Paper Attach

CPRC Recycling Info

Paper Attach

ME DEP Oil Spill Debris Form

[Back to Results](#)


[New Search](#)

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

[Technical Assistance](#) | [Bureau Home](#) | [Maine.gov](#) | [Privacy](#) | [Security](#)



Copyright © 2005 All rights reserved.



MAINE HEALTH AND ENVIRONMENTAL TESTING LABORATORY



221 State Street, Station #12
Department of Human Services
Augusta, Maine 04333
Tel. No. 207-287-1716
Fax. No. 207-287-6832

Office Use Only:
DOR
DEPP
TO BE BILLED

ORGANICS SECTION REPORT

To:
ANDREWS
DEP STA 17
AUGUSTA ME
04333

Test Request Codes:

DROW
Appropriation Number:
01406A1546442

Please Retain This Report for your Invoice Records.

SAMPLE DEMOGRAPHICS AND LOCATION DATA:

HETL Sample Number 97E-DOR-02618 User Number:

Project Name A-331-97 Project Number 2631

Collection Date	Received Date	Analysis Validation Date	Print Date
09/09/97	09/10/97	09/23/97	09/24/97
Sample Matrix		Sample Type	Sampled by
WATER		GRAB	ANDREWS
Sample Location		AUGUSTA	
KIT TAP			
Additional Comments			
PLS CALL WRSETS ASAP WILL...			

ANALYTICAL RESULTS:

FUEL OIL IN WATER-4.1.25 All results are measured as: ug/L
REPORTING LIMIT = 25 ug/L.

Analysis	Analytical Results
DIESEL RANGE ORGANICS	<25
TOTAL HYDROCARBONS	K25
EXTRACTION DATE	09/11/97
ANALYSIS DATE	09/15/97

Comments
ADVISORY LEVEL FOR DIESEL RANGE ORGANICS IS 50 ug/L.
THE SAMPLE WAS TOO WEATHERED TO DETERMINE THE PETROLEUM HYDROCARBON MIXTURE PRESENT.

Summary of Notations used in Reporting Analytical Results:
NC= Not Confirmed NQ= Not Quantitated NA= Not Analyzed J= Approximately
RL= Reporting Limit, the lowest concentration which can be reliably reported on a routine basis
K= Indicates a possible, non-confirmed trace level below the RL
<= less than
Note: Results below the advisory limit, including < and K are considered satisfactory for that parameter.

Analyst: *[Signature]* QC: *[Signature]* 9/15/97

If we can be of further assistance to you, Please Call us at 287-1712, and ask for the Organics Section.

State of Maine
Health and Environmental Testing Laboratory
Station #12, 221 State Street
Augusta, Maine 04333
207-287-1712

LABORATORY RESULTS (FINAL)
MAILED TO:
ANDREWS
DEP STA 17
AUGUSTA ME
04333

Print Date: SEPT 12 1997
Date Validated: 970912

Test Code: TSN

Project Name: A-331-97
Town/County: AUGUSTA
Project Number: 2631
SAMPLER NAME: ANDREWS
SAMPLE DATE: 970909

ANALYST: *J*

QC: *UB*

COMMENTS:

PLS CALL W RSLTS ASAP WILL...

APPROPRIATION #: 01406A1546442

***** Sample and Analysis Information *****

HETL SAMPLE NO. 97E-DOR-06697 USER NO.

Matrix: WATER

Type: GRAB

Location of Sample: KIT TAP

DESCRIPTION OF TEST

RESULTS UNITS

EPA METHOD 524.2

ug/L

THE FOLLOWING COMPOUNDS WERE DETECTED BY THIS METHOD:

ANALYSIS DATE

09/11/97

BENZENE

K0.5

TOLUENE

K0.5

SEE FORM TS524 FOR TEST ANALYTES AND REPORTING LIMITS.

NC= Not confirmed NQ= Not quantitated NA=Not analyzed J=Approximately
RL= reporting limit, the lowest concentration which can be reliably
reported on a routine basis.

K indicates a possible, non-confirmed trace level below the RL.

NOTE: Results below the advisory limit, including < and K are considered
satisfactory for that parameter.